

IN THE DRAWINGS:

B Please replace Fig. 1 with amended Fig.1, attached. The lead lines to reference numerals 42 and 43 were improperly drawn to the improper structural elements in original Fig. 1. As is made clear on page 11, lines 6-8, these reference numerals should have lead lines drawn to the small circumferentially closed openings in uppermost spanning member, such as that properly indicated by reference numeral 40. Amended Fig. 1 corrects the lead line placement for reference numerals 42 and 43. No new matter has been entered.

B Please replace Fig. 3 with amended Fig.3, attached. This figure has been changed to correct an inadvertent error. Previously the projections at the top of panel 50 did not match up with the projections at the top of panel 48, as it should have, as noted at page 12, line 10 of the specification, where it states that "Panel 50 is essentially a mirror image of panel 48". This error was corrected by the drawing change. No new matter has been entered.